

APPENDIX F

DUW 80036384  
BVL

<u>INDUSTRY</u>	<u>ON-SITE</u>	<u>FOLLOW-UP/COMMENT</u>
1. RSR/Bergsoe Metal	1/11/83	Monitoring in Lander Street storm drainage system 2/27/84 Clean out 10/24/84
*2. Lockheed Marine	5/2/83	Scope of Work for Monitoring 5/26/83 Post site conference 3/13/84 Letter describing control measures implemented 4/6/84
*3. Marine Power & Equipment	9/14/83	Letter requesting additional information 10/27/83 Post site visit conference 3/7/84 Response 4/13/84 Referred to DOE 5/3/84 Fined \$5,000 by DOE 7/26/84. Appealed to WPCHB
*4. Jorgensen Steel	10/24/83	NPDES permit and acid pit referred to DOE 11/1/83 Jorgensen response to DOE Hazardous Waste 3/20/84
5. Leckenby	11/9/83	Recommendations that drum storage area be bermed. Facility now closed.
6. Harbor Island Machine Works	11/10/83	Recommendations that oil absorbent pads be available near storm sewer sump. Problem resolved as per letter of 10/10/84
7. Columbia Cement	11/10/83	No additional control measures necessary Letter 11/23/83 Trouble call 10/24/84. Recommended berming wash area 10/25/84
8. Shell Oil	11/15/83	Letter requesting groundwater information 1/24/84
9. ARCO	12/16/83	Request for groundwater information one sample below--scheduled stormwater discharge to river
*10. Todd Shipyards	1/12/84	Post site visit conference 3/6/84 Response letter 4/6/84 Referred to DOE 4/17/84
11. Seattle Iron & Metal	2/8/84	Samples taken 2/29/84 Post site conference 4/16/84 Additional samples 4/27/84 Letter with results, recommendations 10/24/84

Work continuing with  
Industrial Waste Division

DUW 80036385  
BVL

<u>INDUSTRY</u>	<u>ON-SITE</u>	<u>FOLLOW-UP COMMENT</u>
12. Pacific Rendering	2/8/84	No additional control measures necessary
13. Chevron	2/22/84	Request for groundwater data 4/23/84
14. Mobil	3/20/84	No additional control measures necessary
15. Asahipen Paint	3/20/84	No additional control measures necessary
16. Pacific Wire Works	6/20/84	No additional control measures necessary
17. Texaco	6/26/84	Recommendation that trucks be washed in appropriate facility; Requested Groundwater information. Resolved letter of 9/10/84.
18. Non Ferrous Metals	6/21/84	Drain sample taken 7/13/84. Recommendation letter 10/24/84
19. Kipper & Son Fabricators	6/18/84	No additional control measures necessary
20. Meltec	7/19/84	Two samples requested - scheduled
21. Al Bolser Tire Service	unnecessary	Wholesale/Retail Outlet
22. Barco Wiper Supply	unnecessary	(checked I.W)
23. Clean Sound Corp.	unnecessary	Oil spill control. Cleanup occurs off site
24. Duwamish Water Association Marina	unnecessary	Pleasure boat marina
25. ESCO NW Industrial	unnecessary	Wholesale/retail outlet-stainless steel fitting
26. Fisher Mills Inc.	9/7/84	No additional control measures necessary
27. Freight Management Assn.	unnecessary	Barge/tows-Sea/Alaska
28. Global Diving & Salvage	unnecessary	Office & equipment storage
29. Hardware Specialty Co.	unnecessary	Wholesale/marine electrical supply

DUW 80036386  
BVL

<u>INDUSTRY</u>	<u>ON-SITE</u>	<u>FOLLOW-UP COMMENT</u>
47. GTAX Terminals	10/12/84	No additional control measures necessary
*48. Ashgrove Cement	10/10/84	Presite 10/10 Post-site 11/29. Recommended paving berm and cover oil storage area. Requested samples of slag fly ash, coal and surge pond.
*49.† Manson Construction	11/14/84	Presite 11/9
*50. Duwamish Shipyard	11/28/84	Presite 11/15 Post-site 12/6

DUW 80036387  
BVL

\*Member, Duwamish Industrial Council.

<u>INDUSTRY</u>	<u>ON-SITE</u>	<u>FOLLOW-UP/COMMENT</u>
30. North Star Forwarding	unnecessary	Container operation
31. Owens Corning	unnecessary	Insulation contractor/marine division
32. Pacific Molasses	7/23/84	Recommendation that emergency shut-off valve be installed
33. Pilgrim Pet Supply	unnecessary	Wholesale/warehouse
34. Seattle Stevedore	unnecessary	office
35. Value Metal Polishing	unnecessary	Metro I.W. (Denise Healey) DOE lead
36. WIOMC	unnecessary	Industrial medical offices
37. Wyatt Engineers	unnecessary	Engineering offices and warehouse
38. Wycoff	unnecessary	EPA/DOE lead. Storm drain samples 4/5/84
39. Long Painting	8/17/84	No additional control measures necessary
40. Malarkey Asphalt	8/21/84	Samples taken of pone 10/22/84, river bank sediment 10/23/84
41. Richardson & Holland	8/22/84	No additional control measures necessary
42. Purdy Company	9/17/84	Recommended recycling used oil, avoid transformers with PCB's
43. Ideal Basic Industries	10/10/84	Presite 9/26; letter of 10/22, No additional control measures necessary
*44. Monsanto	10/2/84	Presite 9/14; Telephone post site 10/10; Letter 10/18/84, No additional control measures necessary
*45. Kenworth	10/2/84	Presite 9/19; Telephone post site 10/10; Letter 10/23 No additional control measures necessary
*46. Northwest Glass	10/2/84	Presite 9/14; Telephone post site, 10/26. Recommended burm, cover of oil drum storage area. Resolved, letter of 11/6/84. No additional control measures necessary.

DUM 80036388  
 BVL